
Motor is bad
Motor = Off
Timeout
Motor = On
P = E = 0
P = 1
Motor = On
P = 1, E = 0
Timeout
Motor = Off
E is broken
E = 1
E = 0
E = 1
Motor = Off
P is broken
Timeout
Motor = On
P = 0, E = 1
P = 0
Motor = Off
P = E = 1
P = 1